PHILIPS Lighting



MSR Gold™ MiniFastFit – lamp replacement in seconds

MSR Gold™ MiniFastFit (DJ/Club)

Thanks to the specially designed lamp base and lamp holder, the MSR Gold[™] MiniFastFit takes just seconds to replace, to help ensure non-stop clubbing entertainment. In addition, the innovative gold plated pins ensure excellent current transfer to prolong lamp and lamp holder lifetimes and thereby reduce lamp replacement costs. Easy handling and small compact fixture designs are allowed by the lamps compact size, while the very short arc provides a high perceived brightness and high beam intensity.

Benefits

- \cdot Lamp replacement in just seconds
- $\boldsymbol{\cdot}$ Easy handling, smaller and lighter fixtures
- $\boldsymbol{\cdot}$ Reduces early lamp or lamp holder failures. Excellent current transfer
- \cdot High perceived brightness
- High beam intensity

Features

- Philips MiniFastFit
- $\cdot \text{ Compact design}$
- \cdot Innovative gold plated pins
- Color temperature >8000K
- \cdot Very short arc

MSR Gold[™] MiniFastFit (DJ/Club)

Application

- Events
- Shows
- DJ/Club

Warnings and Safety

• A lamp breaking is extremely unlikely to have any impact on your health. If a lamp breaks, ventilate the room for 30 minutes and remove the parts, preferably with gloves. Put them in a sealed plastic bag and take it to your local waste facilities for recycling. Do not use a vacuum cleaner.

Versions



MSR Gold™ 300/2 MiniFastFit

Dimensional drawing

D

Product	D (max)	0	L (min)	L (max)	L	C (max)
MSR Gold™ 300/2	23 mm	5.0 mm	65.8 mm	67.8 mm	66.8 mm	126 mm
MiniFastFit 1CT/4						



© 2020 Signify Holding All rights reserved. Signify does not give any representation or warranty as to the accuracy or completeness of the information included herein and shall not be liable for any action in reliance thereon. The information presented in this document is not intended as any commercial offer and does not form part of any quotation or contract, unless otherwise agreed by Signify. All trademarks are owned by Signify Holding or their respective owners.

www.lighting.philips.com 2020, May 6 - data subject to change